
Dell Optiplex DA-1 (ADP-150BB) & DA-2 (ADP-220AB)

Posted by Ralph - 2008/08/11 18:35

Dell Optiplex DA-1 (ADP-150BB B) and DA-2 (ADP-220AB) AC adapters
for Optiplex SX260 (DA-1) and SX280 (DA-2)

The following pictures are showing both pinouts

DA_1 type

http://www.avi-plus.com/images/fbfiles/images/Dell_DA-1_pinout.png

DA-2 type

http://www.avi-plus.com/images/fbfiles/images/Dell_DA_2_pinout-9370dc57c6c00b7aed405a6389370422.png

Remote PIN should be connected to ground in order to activate the PSU
(Only one is necessary)

Regards

Ralph

=====

Re:Dell Optiplex DA-1 (ADP-150BB) & DA-2 (ADP-220AB)

Posted by Ralph - 2008/09/30 08:32

Information on death DELL OPTIPLEX PSU :

There is a fuse inside ! This is a low speed fuse 6.3A T.

When the fuse blows again after replacement, double check the power silicon rectifier
bridge type KBU8A - KBU8M.

If necessary (when in short circuit), replace it and install a new fuse.

=====